

Maximum Performance and Lifespan Designed to last longer than 4,000 times



Check out further details about SPIN features on our website

BY FRICTION


10

CRACKS AND LEAKS





WWW.FLARINGSPIN.COM





PATENT PENDING

ACCESS OUR YOUTUBE CHANNEL AND CHECK FOR MORE INFORMATION ABOUT MIGRARE SPIN TOOLS flaringspin.com/youtube



Product Documentation

Thank you for purchasing your new Swaging SPINs and welcome to the high temperature leakage-free flaring concept, designed from the ground up to HVAČ systems.

The documentation for this product includes this User's Manual and the complementary Technical Documentation, available for download at www. flaringspin.com. Complementary instructional videos are also available at www.flaringspin.com/ videos

For reaching maximum performance out of the use of your Swaging SPIN tool, carefully read these instructions and keep this manual for further reference

Packaging Content

The Swaging SPIN set SSPIN300 includes 6 Swaging Diameters



Extra Features





Up to 10x faster than conventional tools

Works either No reaming with a corded or a process cordless drill* reauired**

**Cleaning the tubing is a standard procedure in any air conditioning system. The use of the SPIN Tools does not exclude the user from doing this procedure.

Safety Information

Read and follow these instructions carefully:



The Swaging SPINs use a HIGH TEMPERATURE technology. due to friction between the metallic tube and the tool. For your safety, consider it HOT at all times




Wait until the metallic tube and the tool to cool down before placing your hand onto the tube or the tool surface.



Always use protective gloves while working with the Swaging SPIN, SFI LEVEL 10 protection aloves. Direct skin contact with the tube or the tool may result in serious injuries and burns.

Always keep the Swaging SPIN well attached and fastened into the power tool you are using (Corded Drills, Cordless drills).



while working with the Swaging SPIN. ANSI Z87.1 eye protection (CAN/CSA Z94.3). Occasionally, chips may occur during the swaging process and may get to your eyes, causing severe injuries, burns or even loss of vision.


Do not use any loose clothing and jewelry or approach the tool with loose long hair during the operation of the tool, as it may entangle and get caught around it, causing serious personal injury.

Stay alert, watch what you are doing and use common sense when operating the Swaging SPIN. Do not use the Swaging SPIN while you are tired or under the influence of drugs, alcohol or medication. A moment of inattention while operating the Swaging SPIN may result in serious personal injurv.

Store the tools out of the reach of children and do not allow people unfamiliar with the swaging tool or these instructions to operate the swaqing tool.

Instructions for Use

1. Make sure the tubing is firmly held at all times. You may use your other hand to do it. Keep a safe distance between your hand and the tube's border.



 Fasten the Swaging SPIN correspondent to the tube diameter, into the drill/screwdriver's chuck, making sure it is not loose.




3. Make sure the HAMMERING MODE is OFF.




Turn ON, pull the trigger and keep the drill/ screwdriver at MAXIMUM SPEED, at all time.


 Keep the tube ALIGNED to the drill/screwdriver at all time and PUSH the Swaging SPIN all the way in, applying a CONSTANT PRESSURE, until the Stopper hits the tube.




6. Keeping the tube ALIGNED to the drill/ screwdriver and also keeping the drill/screwdriver at MAXIMUM SPEED, pull off the Swaging SPIN from inside the tube. Remember: the whole swaging process, in and out, shouldn't take more than 5 to 7 seconds.



 Right after the swaging process, the tube temperature is very high. Don't touch it. Wait the heat to dissipate before touching the swage.



8. Assemble the fittings as usual.



*Minimum Requirements

The SPIN tools are designed to work along with drills and/or screwdrivers, with minimum of 1,800 RPM and 500 watts for corded drills, or superior and 1,800RPM and 18V, or superior, for cordless drills.

Using the SPIN tools along with less powerful equipment may result in high decrease of performance.

Customer Service



Cimport International LLC info@flaringspin.com +1-203-587-0336

www.flaringspin.com