


Goodman




Replaces		
B2833001S	B2833001	7021-9000
7021-9087	FB-RFB140	
Item ID	A140	
H.P.	1/50	
Volts	115	
RPM	3400	
Amps	1.40	
Speeds	1	
Type	Shaded Pole	
Bearings	Sleeve	
Enclosure	Open	
Hertz	60	
Overload	Automatic	

Goodman




Replaces		
B295900	7021-8656	
Item ID	A162	
H.P.	1/50	
Volts	208-230	
RPM	3000	
Amps	0.50	
Speeds	1	
Type	Shaded Pole	
Bearings	Sleeve	
Enclosure	Open	
Hertz	60	
Overload	Automatic	

Goodman



Replaces		
B4059000	7002-3036	
Item ID	A182	
H.P.	1/35	
Volts	115	
RPM	3125	
Amps	1.20	
Speeds	1	
Type	Shaded Pole	
Bearings	Sleeve	
Enclosure	Open	
Hertz	60	
Overload	Automatic	




Goodman

Replaces		
B4059000	J238-112-11195	7002-3036
J238-11195		
Item ID	66590	
H.P.	1/30	
Volts	115	
RPM	3000	
Amps	1.50	
Speeds	1	
Type	Shaded Pole	
Bearings	Ball	
Enclosure	Open	
Hertz	60	
Overload	Automatic	

Goodman



Replaces		
B1859005	J238-11128	
Item ID	66002	
H.P.	1/30	
Volts	115	
RPM	3000	
Amps	1.60	
Speeds	1	
Type	Shaded Pole	
Bearings	Ball	
Enclosure	Open	
Hertz	60	
Overload	Automatic	



Goodman

Replaces		
0131M00002P	0131M00002S	
119276-00		
Item ID	66002	
H.P.	1/35	
Volts	115	
RPM	3000	
Amps	1.90	
Speeds	1	
Type	Shaded Pole	
Bearings	Ball	
Enclosure	Open	
Hertz	60	
Overload	Automatic	
Includes	Gasket	

Heil-Quaker



Replaces		
5C085	610672	HQ610672
Item ID	A064	
H.P.	1/55	
Volts	115	
RPM	3150	
Amps	0.70	
Speeds	1	
Type	Shaded Pole	
Bearings	Sleeve	
Enclosure	Open	
Hertz	60	
Overload	Automatic	



ICP

Replaces		
1012002	1013388A	
1014338		
Item ID	66338	
H.P.	50 MHP	
Volts	115	
RPM	3000	
Amps	2.40	
Speeds	1	
Type	Shaded Pole	
Bearings	Ball	
Enclosure	Totally Enclosed	
Hertz	60	
Overload	Automatic	