




# Welding Gauges



**G15D**

**1 1/2" GAUGES**  
[1/8" NPT]

**2" GAUGES**  
[1/4" NPT\*\*]

**2 1/2" GAUGES**  
[1/4" NPT\*\*]

Pressure Calibration	1 1/2" GAUGES [1/8" NPT]		2" GAUGES [1/4" NPT**]		2 1/2" GAUGES [1/4" NPT**]		
	Powder Painted Steel Case B.M.	Gold Steel Case C.B.M. WITH WEEP HOLE	Brass Case B.M.	Brass Case C.B.M.	Gold Steel Case B.M.	Brass Case B.M.	Gold Steel Case B.M.
15 PSI	G20D [BLUE]	-	-	-	-	-	-
30 PSI [Red Line 15-30]	G15D*	-	-	-	-	-	-
30 PSI [Red Line 15-30]	G79D	-	G2D	-	G2SD	G22D	G22SD
30 PSI	G80D	-	G74D	-	G74SD	G75D	G75SD
60 PSI	G83D*	-	G5D	G105	G5SD	G25D	G25SD
100 PSI	G49D*	G185	G6D	G106	G6SD	G26D	G26SD
200 PSI	G78D	G178	G4D	G104	G4SD	G24D	G24SD
300 PSI	G84D*	G184	G33D	-	G33SD	-	-
400 PSI	G73D	-	G1D	G101	G1SD	G21D	G21SD
1/4, 1/2, 3/4, FULL	G19D*	-	-	-	-	-	-
600 PSI	-	-	G8D	G108	G8SD	G28D	G28SD
1000 PSI	-	-	G34D	-	G34SD	-	-
3000 PSI, (L) LISTED	-	-	-	-	G3SD	-	-
4000 PSI, (L) LISTED	G56D*	G182	G7D	-	G7SD	G27D	G27SD
6000 PSI, (L) LISTED	-	-	G44D	-	G44SD	G46D	G46SD

B.M. = Bottom Mount. C.B.M. = Center Back Mount. \* With Gauge Boot.

\*\* For 1/8" NPT add [-4] to Part Number.

## Replacement Lenses



**GB15S**  
1 1/2" Gauge Boot Set Black

	Part#	1 1/2" Description	Part#	2" Description	Part#	2 1/2" Description
DISPLAY CARD	PL15	Posi-Lock	PL2	Posi-Lock	PL25	Posi-Lock
BULK	05-1-52	Flat Plastic	05-2-52-4	Flat Plastic	05-3-52-8	Posi-Lock
	05-1-52-7	Posi-Lock	05-2-52-7	Posi-Lock		
	05-1-63	Friction Ring	05-2-63-2	Friction Ring		

**GB20S**  
2" Gauge Boot Set Black



Uniweld Products, Inc. Fort Lauderdale, FL 33312 U.S.A. Customer Service: 800.323.2111  
info@uniweld.com • www.uniweld.com

Gauges/Thermometers