Temperature / RH% Tools HVACR Pros Trust |44

# Psychrometer Accessory Head

### ARH5

The ARH5 measures and calculates from inside the duct for more measurements.

- Measures temps and %RH
- Calculates wet bulb dew point
- Fast, accurate results target superheat and evaporator exit temperature



Stabilizing cone - RCONE1



# T1 T2 Rayse theremoverse Plant Temperature (1940 © Head Sat meter to mVDC range to display temperature directly temperature circum. True: True:

## Dual Temperature Accessory Head

### ATH4

Measures two temperatures simultaneously to output T1, T2, or T1-T2

- ±1°F accuracy
- Select °F or °C
- Range: -50°F to 1800°F
- Superior temp compensation



# Gun Style IR Thermometer with Laser

### SIG1

The SIG1 takes accurate surface temperatures. The narrow 10:1 field of view allows techs to target smaller areas.

- 10:1 field of view
- Select °F or °C
- Range: -22°F to 1022°F

# IR Thermometer with Laser

### SIR2

Ergonomic pocket IR with laser.

- 6:1 field of view
- MIN/MAX automatic data hold
- Select °F or °C





# **Rod and IR Temperatures SPK3**

### **Convenient 2-Way Temp.**

Easy to use compact tool for quick in-duct, register, and ambient temperatures.

- 8:1 IR
- Hands free in-duct temps
- Ouick T1-T2 calculations
- Max/min/hold