



Data Sheet

Operator Replacement Series Type RA or RAV to RA 2000

Selection:



**Identifiable
mounting:**

Large silver threaded nut

RA SERIES

Valve mounted dial
013-7001 RA-6
013-7101 RA-6 "Armored"

RA SERIES

Remote mounted dial
013-7002 RA33
013-7003 RA-36
013-7004 RA-66

RA 2000

013G8070
RA valve to
RA 2000
operator adapter

+

013G8252
or
013G2922
or **013G8564**
(6' + 6' cap. tube)

or

or **013G8562**
(6' cap. tube)
or
013G8565
(16' cap. tube)
or
013G8568
(26' cap. tube)

RA 2000

013G8070
RA valve to
RA 2000
operator adapter

+

013G8564
(6' + 6' cap. tube)

or

or **013G8562**
(6' cap. tube)
or
013G8565
(16' cap. tube)
or
013G8568
(26' cap. tube)

RAV SERIES

Valve mounted dial/sensor
013U8200 RAV "Built-in"
013U1100 RAVN "Built-in"

RAV SERIES

Valve mounted dial/sensor
013U8202 RAV "Remote"
013U1102 RAVN "Remote"

RA 2000

013G8072
RAV valve to
RA 2000
operator adapter

013G8250 or **013G8240**
(tamper proof)

RA 2000

013G8072
RAV valve to
RA 2000
operator adapter

013G8252
or
013G2922
(tamper proof)

**Identifiable
mounting:**

Black or silver metal band
with flat screw holding the
operator to the valve




Selection (Cont.):

**Existing (OLD)
Operator Types**


Separate remote sensor/dial (RAV/RAVL)
013U2241
or 013U2211 (BRAVO)

013U7151 RAV-33
or 013G8222




Separate remote sensor/dial (RAV/RAVL)
013U2241
or 013U2211 (BRAVO)

013U7151 RAV-33
or 013G8222




**Replacement (NEW)
Operator Types**

NOTE:
RA 2000 wall mount operators include additional socket for use on RAV valves. RAV Adapter included



013G8564
(6' + 6' cap. tube)



013G8562
(6' cap. tube)
013G8565
(16' cap. tube)
013G8568
(26' cap. tube)

→


Selection (Cont.):

Code No.	Type	Description
013G8070	RA service adapter	RA valve to RA 2000 operator adapter
013G8072	RAV service adapter	RAV valve to RA 2000 operator adapter


Note: Consult RA 2000 Data sheet for additional or technical information

Selection (Cont.):

RA to RA 2000 - Code no. 013G8070



RAV to RA 2000 - Code no. 013G8072



Danfoss can accept no responsibility for possible errors in printed materials and reserves the right to alter its products without notice. All trademarks in this material are property of the respective companies. Danfoss and Danfoss logotype are trademarks of Danfoss A/S. All rights reserved.



Danfoss Inc.
Toronto, ON
Toll Free: 866-375-HVAC (4822)
Tel.: 905-285-2050, Fax: 905-285-2055
www.na.heating.danfoss.com

Danfoss Inc.
Baltimore, MD
Toll Free: 866-375-HVAC (4822)
Tel.: 443-512-0266, Fax: 443-512-0270
www.na.heating.danfoss.com